

Ventilation Inspection Checklist

Day School

No change as of 25th October 2023

Natural-**N** Mechanical – Supply and extract - **MSR** Mechanical – Heat recovery – **MHR**

Mechanical – Extract only – **MEO** Mechanical – air conditioning - **MAC**

Specialised localised exhaust ventilation – **SLEV** No ventilation – **NV** Not known - **NK**

Pamis No.	Location	Ventilation type	Transfer / relocation of air : Yes/No	Comments
	Main entrance	N	No	
	Main office	N	No	
141	Dining room	N	No	
143	Kitchen	N	No	
144	Assistant Head office	N	No	
145/146	Sensory suite	MSR	No	
146	Ladies toilet	N	No	
148	Gents toilet	N	No	
151	Music room	N	No	
116	14-16 classroom	N*/MEO/MAC	No	*Only via internal & external door
121	14-16 classroom	N	No	
122	14-16 classroom	N	No	
118	Common room	N	No	
119	Toilet	N/MEO	No	
140	Small bathroom	N/MEO	No	
	Bursar office	N	No	
	Head office	N	No	
137	Big bathroom	N/MEO	No	
125	Primary 2	N	No	
128	Primary 2 bathroom	N	No	
127	Primary 1	N	No	
131	Primary 1	N	No	
160	Primary 1 bathroom	N	No	
134	Secondary	N	No	
153	Deputy Head office	N	No	

	Dining room/old FE			
161	Entrance lobby	N	No	
162	Toilet	N/MEO	No	
163	Dining room	N	No	
	Outside classrooms			
	Small	N	No	
	Large	N	No	