

Ventilation Inspection Checklist

Residential Building

No change as of 31st March 2023

Natural - **N** Mechanical – Supply and extract - **MSR** Mechanical – Heat recovery – **MHR**

Mechanical – Extract only – **MEO** Mechanical – air conditioning - **MAC**

Specialised localised exhaust ventilation – **SLEV** No ventilation – **NV** Not known - **NK**

Ground floor				
Pamis No.	Location	Ventilation type	Transfer / relocation of air : Yes/No	Comments
20	Office/workroom	N	No	
21/23	Kitchen	N/MEO/SLEV	No	
13/14	Laundry	N/MEO	No	
26	Gents toilet	N	No	
29	Ladies toilet	N	No	
33	Swimming pool Office	N	No	
34	Swimming pool	N/MAC	No	
35	Swimming pool Gents changing area	MEO	No	
36	Swimming pool Ladies changing area	MEO	No	
37	Swimming pool conservatory	N	No	
11	Reprographics room	N/MEO	No	
9	Therapy room	N	No	
7	Small bathroom	N/MEO	No	
39	Lounge	N	No	
41	Dining room	N	No	
43	Library	N	No	
44	16 – 19 Classroom	N*	No	*External door only
45	16 – 19 DT	N	Yes*	*From adjacent room when connecting door open
49	PE Hall	N	No	
50	Assistant Head Office	N	No	
4	Gents WC	N/MEO	No	
3	Ladies WC	N/MEO	No	
5	Big bathroom	N/MEO	No	

Pamis No.	Location	Ventilation type	Transfer / relocation of air : Yes/No	Comments
51/52/54	Basement cellar store	NV	No	
55/56/57	Boiler room	NV	No	
First and Second floor				
Second Floor				
104	Parent's bedroom	N	No	
105	Staff shower/WC	N	No	
106	Staff shower	N	No	
102	Staff bedroom	N	No	
101	Staff bedroom	N	No	
100	Staff bedroom	N	No	
99	Staff bedroom	N	No	
First Floor				
79	Clock View	N	No	
78	Sensory bathroom	N/MEO	No	
76	Church View	N	No	
74	Pupil bathroom	N/MEO	No	
71	Care Manager office	N	No	
68	Pupil bedroom	N	No	
69	Disable toilet	N	No	
65	Conference room	N	No	
62	Staff room	N	No	
60	Cove View	N	No	
61	Cove View	N	No	
95	Village View	N	No	
93	Leighton View	N	No	
92	Leighton View	N	No	
82	Nurses old office	N	No	
84	Meds. prep room	N	No	
85	Pupil bedroom	N	No	
87	Pupil bedroom	N	No	

88	Residential staff office	N	No	
Pamis No.	Location	Ventilation type	Transfer / relocation of air : Yes/No	Comments
89	Toilet	N	No	
90	Staff/Pupil bathroom	N	No	
Rebound room		N	No	
Conservatory		N	No	