

Ventilation Inspection Checklist

Residential Building

No change as of 25th October 2023

Natural - **N** Mechanical – Supply and extract - **MSR** Mechanical – Heat recovery – **MHR**

Mechanical – Extract only – **MEO** Mechanical – air conditioning - **MAC**

Specialised localised exhaust ventilation – **SLEV** No ventilation – **NV** Not known - **NK**

| Ground floor | | | | |
|--------------|------------------------------------|------------------|---------------------------------------|---------------------|
| Pamis No. | Location | Ventilation type | Transfer / relocation of air : Yes/No | Comments |
| 20 | Office/workroom | N | No | |
| 21/23 | Kitchen | N/MEO/SLEV | No | |
| 13/14 | Laundry | N/MEO | No | |
| 26 | Gents toilet | N | No | |
| 29 | Ladies toilet | N | No | |
| 33 | Swimming pool Office | N | No | |
| 34 | Swimming pool | N/MAC | No | |
| 35 | Swimming pool Gents changing area | MEO | No | |
| 36 | Swimming pool Ladies changing area | MEO | No | |
| 37 | Swimming pool conservatory | N | No | |
| 11 | Reprographics room | N/MEO | No | |
| 9 | Therapy room | N | No | |
| 7 | Small bathroom | N/MEO | No | |
| 39 | Lounge | N | No | |
| 41 | Dining room | N | No | |
| 43 | Library | N | No | |
| 44 | 16 – 19 Classroom | N* | No | *External door only |

| | | | | |
|----|-----------------------|-------|------|---|
| 45 | 16 – 19 DT | N | Yes* | *From adjacent room when connecting door open |
| 49 | PE Hall | N | No | |
| 50 | Assistant Head Office | N | No | |
| 4 | Gents WC | N/MEO | No | |
| 3 | Ladies WC | N/MEO | No | |
| 5 | Big bathroom | N/MEO | No | |
| | | | | |

| | | | | |
|-------------------------------|-----------------------|-------------------------|--|-----------------|
| | | | | |
| Pamis No. | Location | Ventilation type | Transfer / relocation of air : Yes/No | Comments |
| 51/52/54 | Basement cellar store | NV | No | |
| 55/56/57 | Boiler room | NV | No | |
| | | | | |
| First and Second floor | | | | |
| Second Floor | | | | |
| | | | | |
| 104 | Parent's bedroom | N | No | |
| 105 | Staff shower/WC | N | No | |
| 106 | Staff shower | N | No | |
| 102 | Staff bedroom | N | No | |
| 101 | Staff bedroom | N | No | |
| 100 | Staff bedroom | N | No | |
| 99 | Staff bedroom | N | No | |
| First Floor | | | | |

| | | | | |
|------------------|--------------------------|-------------------------|--|-----------------|
| 79 | Clock View | N | No | |
| 78 | Sensory bathroom | N/MEO | No | |
| 76 | Church View | N | No | |
| 74 | Pupil bathroom | N/MEO | No | |
| 71 | Care Manager office | N | No | |
| 68 | Pupil bedroom | N | No | |
| 69 | Disable toilet | N | No | |
| 65 | Conference room | N | No | |
| 62 | Staff room | N | No | |
| 60 | Cove View | N | No | |
| 61 | Cove View | N | No | |
| 95 | Village View | N | No | |
| 93 | Leighton View | N | No | |
| 92 | Leighton View | N | No | |
| 82 | Nurses old office | N | No | |
| 84 | Meds. prep room | N | No | |
| 85 | Pupil bedroom | N | No | |
| 87 | Pupil bedroom | N | No | |
| 88 | Residential staff office | N | No | |
| Pamis No. | Location | Ventilation type | Transfer / relocation of air : Yes/No | Comments |
| 89 | Toilet | N | No | |
| 90 | Staff/Pupil bathroom | N | No | |
| | | | | |

| | | | | |
|---------------------|--|---|----|--|
| Rebound room | | N | No | |
| | | | | |
| Conservatory | | N | No | |